



C&D ACCESS

Case Study – Hydraulic RAM Replacement

Hydraulic RAM Replacement

The image shows two workers performing a hydraulic RAM replacement on a ship's hull. One worker in blue gear is positioned higher up, while another in orange gear is lower down. They are using ropes and a large black hook with red straps to manage the equipment. The background is the grey, choppy water of the sea.


Rope Access

C&D Access were tasked to perform a hydraulic RAM replacement and Eddy Current inspection due to overloading of subsea entrenching scissor frame. The works were carried out in a 24 hours window allowing our Client to resume operations.

Contact us

Our dedicated customer service department are more than happy to assist with any enquiries or technical queries. Please feel free to contact us via our website, email or telephone.

C&D Access



C&D Access



+44 (0) 191 691 7300



info@cdais.co.uk



www.cdais.co.uk