



# C&D ACCESS

*Case Study – Deconstruction of Conveyor – SIMEC Power SUF*

# Deconstruction of conveyor structure

A large industrial crane is lifting a metal conveyor structure over a body of water. The structure is suspended by cables and is being moved from one location to another. The background shows a hazy sky and a body of water.


## Deconstruction

C&D Access carried out deconstruction of redundant conveyor structure. Some of the main structural member suffered from heavy corrosion and loss of material presenting a high risk structural failure and of drop objects.

## Case study video

Watch [here](#) our video case study.

C&D Access



C&D Access



+44 (0) 191 691 7300



info@cdais.co.uk



www.cdais.co.uk