



C&D ACCESS

Case Study – Fabric Maintenance of Jetty Unloader

Fabric Maintenance of Jetty Unloader

The image shows two workers in blue and yellow safety gear performing maintenance on a yellow metal structure. They are using ropes to access the structure. The structure has yellow railings and a yellow beam with black text that reads "PNT 0409 SWL 3TE". The background shows a body of water and industrial structures.


Rope Access

C&D Access carried out fabric maintenance of Jetty Unloader by means of rope access in an ATEX environment applying specialised surface tolerant coating.

Cost effective

Rope access eliminates the need for scaffolding and reduces the cost and time scale when fabric maintenance projects are to be carried out at height.

C&D Access



C&D Access



+44 (0) 191 691 7300



info@cdais.co.uk



www.cdais.co.uk